

**Risk-Based Inspection – Flyash Erosion on Boiler Tube at Coal-Fired Power Plant**

by

Mohamad Hasrul Hilmi b. Khairul Aman

Dissertation submitted in partial fulfillment of

the requirements for the

Bachelor of Engineering (Hons)

(Mechanical Engineering)

JUNE 2010

Universiti Teknologi PETRONAS

Bandar Seri Iskandar

31750 Tronoh

Perak Darul Ridzuan

## Table of Contents

<b>CERTIFICATION OF APPROVAL</b> .....	<b>i</b>
<b>CERTIFICATE OF ORIGINALITY</b> .....	<b>ii</b>
<b>ABSTRACT</b> .....	<b>iii</b>
<b>ABSTRACT</b> .....	<b>iv</b>
<b>CHAPTER 1: INTRODUCTION</b> .....	<b>1</b>
1.1 Background.....	1
1.2 Problem Statement.....	2
1.3 Objective and Scope of Study.....	2
<b>CHAPTER 2: LITERATURE REVIEW AND THEORY</b> .....	<b>3</b>
2.1 Coal-Fired Thermal Power Plant.....	3
2.2 Brief Analysis on Erosion Rate .....	6
2.3 Flyash Erosion .....	8
2.3.1 Features of Failure .....	8
2.3.2 Locations of Failures .....	9
2.4 Boiler Tube Material .....	10
2.5 Risk-Based Inspection (RBI).....	10
2.5.1 Qualitative Analysis .....	10
2.5.2 Semi-Quantitative Analysis .....	10
2.5.3 Quantitative Analysis .....	11
2.6 Consequence Analysis for Steam .....	12
2.6.1 Estimation of Maintenance Cost.....	12
2.6.2 Estimation of Production Loss Cost .....	14
2.6.3 Down Time.....	14

<b>CHAPTER 3: METHODOLOGY/PROJECT WORK.....</b>	<b>13</b>
3.1 Project Implementation Approach.....	15
3.1.1 Obtaining Boiler Database .....	16
3.1.2 Damage Mechanism Study & Release Event Tree .....	16
3.1.3 Semi-Quantitative Analysis .....	17
3.1.4 Risk Ranking.....	25
3.1.5 Risk Result Comparison.....	25
<b>CHAPTER 4: RESULT AND DISCUSSION .....</b>	<b>26</b>
4.1 Release Event Tree .....	26
4.2 Downtime Analysis .....	27
4.3 API 581 Probability of Failure Analysis.....	28
4.4 API 581 Consequence of Failure Analysis .....	28
4.5 Proposed Consequence of Failure Analysis.....	31
<b>CHAPTER 5: CONCLUSION AND RECOMMENDATION .....</b>	<b>35</b>
5.1 Conclusion .....	35
5.2 Recommendation.....	36
<b>REFERENCES.....</b>	<b>37</b>
<b>APPENDICES .....</b>	<b>39</b>

## List of Figures

- Figure 1: Typical Diagram of a Coal-Fired Thermal Power Plant  
Figure 2: Simplified Steam Generator Schematic  
Figure 3: Dependence of Erosion on Particle and Velocity and Flyash Loading  
Figure 4: Typical Boiler Locations Where Flyash Erosion Can Occur  
Figure 5: Risk Evaluation Process of Qualitative, Semi-quantitative and Quantitative RBI Approaches based on API Code  
Figure 6: Analysis of Downtime  
Figure 7: Project Implementation Stages  
Figure 8A: Determination of Technical Module Subfactors for Thinning  
Figure 8B: Determination of Technical Module Subfactors for Thinning  
Figure 9: Determination of Business of Interruption Cost  
Figure 10: RBI Release Event Tree  
Figure 11: Shortest Downtime Period  
Figure 12: Longest Downtime Period  
Figure 13: API 581 Semi-Quantitative Approach Risk Matrix for A-213 T22  
Figure 14: API 581 Semi-Quantitative Approach Risk Matrix for A-213 T91  
Figure 15: Proposed Semi-Quantitative Approach Risk Matrix for A-213 T22 (Longest Downtime)  
Figure 16: Proposed Semi-Quantitative Approach Risk Matrix for A-213 T91 (Longest Downtime)  
Figure 17: Proposed Semi-Quantitative Approach Risk Matrix for A-213 T22 (Shortest Downtime)

## List of Tables

- Table 1: Classification of Coals by Abrasion Propensity  
Table 2: Labour Rates  
Table 3: Equipment Damage Cost for Carbon Steel  
Table 4: Material Cost Factor  
Table 5: Classification of Boiler Tube Data  
Table 6: TMSF Conversion  
Table 7: Consequence Category