

TABLE OF CONTENTS

CERTIFICATIONS	i
ABSTRACT	iii
ACKNOWLEDGEMENTS.	iv
ABBREVIATION	v
CHAPTER 1:	INTRODUCTION	1
	1.1 Background of Study	1
	1.2 Problem Statement	2
	1.3 Objectives and Scope of Study	2
CHAPTER 2:	LITERATURE REVIEW	4
	2.1 Failure Analysis	4
	2.2 Carbon Steel	4
	2.3 Corrosion of Carbon Steel	5
	2.3.1 Classification of Corrosion	6
	2.3.1.1 Aqueous Corrosion	7
	2.3.2 Forms of Corrosion	8
	2.3.2.1 Localized Corrosion	8
	2.4 Steel Tubular Manufacture Process	12
	2.4.1 Steel Tubular Heat Treatment.	12
	2.4.2 Mechanical Properties of Steel	13
	2.4.3 Chemical Composition of Steel	13
	2.5 Background History	14
	2.6 Similar Cases Happen.	15
	2.6.1 Case I	15
	2.6.2 Case II	15
CHAPTER 3:	METHODOLOGY	16
	3.1 Procedure for Failure Analysis	16
	3.2 Gantt Chart	21
	3.3 Tool/Equipment Required	21
CHAPTER 4:	RESULTS AND DISCUSSION	22
	4.1 Visual Examinations	22
	4.1.1 Steel Tubular Product (before operation)	22
	4.1.2 Steel Tubular Product (after operation)	24
	4.2 Nondestructive Testing	27

4.3	Mechanical Testing	27
4.4	Metallography	28
4.4.1	Macroscopic and Microscopic Examinations (before operation)	29
4.4.2	Macroscopic and Microscopic Examinations (after operation)	30
4.5	Fractography	33
4.5.1	Scanning Electron Microscopy	35
CHAPTER 5:	CONCLUSION AND RECOMMENDATION	40
5.1	Conclusion	40
5.2	Recommendation	40
REFERENCES	42
APPENDICES	43

LIST OF FIGURES

Figure 2.1	Multiple holes detected at 2403.71m MDBDF	14
Figure 3.1	Abrasive Cutter Machine	18
Figure 3.2	Grinder Machine	19
Figure 3.3	Polisher Machine	19
Figure 3.4	Optical Microscope	19
Figure 3.5	Scanning Electron Microscope	21
Figure 4.1	The grade L80 pipe of new steel tubular	22
Figure 4.2	Photograph showing the internal surfaces of seamless tube	23
Figure 4.3	Close-up photograph on internal surfaces of seamless tube	24
Figure 4.4	The internal surface of tubing cut sample	25
Figure 4.5	The internal surface of tubing cut sample showing extensive pitting	25
Figure 4.6	The external surface of tubing cut sample showing extensive pitting	26
Figure 4.7	The magnetic particle inspection on tubing cut sample	27
Figure 4.8	The optical micrograph of Fe-0.4C. 2% Nital etchant. Mag. 200x	29
Figure 4.9	The scanning electron micrograph of Fe-0.4C. Mag. 2000x	29
Figure 4.10(a)	The optical micrograph of Fe-0.4C. 2% Nital etchant. Mag. 200x	30
Figure 4.10(b)	The optical micrograph of Fe-0.4C. 2% Nital etchant. Mag. 200x	30
Figure 4.11	The scanning electron micrograph of Fe-0.4C. Mag. 2000x	32
Figure 4.12	The scanning electron micrograph of Fe-0.4C. Mag. 2000x	32
Figure 4.13(a)	Photograph showing a cross-section of internal region of the tube through wall hole area (pointed by arrow)	33
Figure 4.13(b)	Photograph showing a cross-section of internal surface of the tube at the hole area (region marked red)	34
Figure 4.13(c)	Photograph showing a cross-section of external surface of the tube at the hole area (pointed by arrow)	34
Figure 4.14	The scanning electron fractograph of Fe-0.4C. (a) Mag. 50x (b) Mag. 200x	36 36
Figure 4.15	The EDX elemental analysis results of the internal side of the tube through wall hole area	37

Figure 4.16	The corrosion product analysed using EDX. Mag. 500x	38
Figure 4.17	The EDX analysis of the corrosion product showed a marked presence of iron oxides and chlorine	38

LIST OF TABLES

Table 2.1	Mechanical Properties of Steel Tube	13
Table 2.2	Chemical Composition of Steel Tube	13
Table 4.1	Rockwell 'C' hardness measurement (HRC) of tube after operation	28
Table 4.2	Chemical analysis (wt%) of the failed tube at the hole area	37