

CONTENTS

CERTIFICATION OF APPROVAL.....	i
CERTIFICATION OF ORIGINALITY.....	ii
ABSTRACT.....	iii
ACKNOWLEDGEMENT.....	v
LIST OF FIGURES.....	vi
LIST OF TABLES.....	ix
LIST OF ABBREVIATIONS.....	x
CHAPTER 1 : INTRODUCTION.....	Error! Bookmark not defined.
1.1 BACKGROUND OF STUDY.....	Error! Bookmark not defined.
1.2 PROBLEM STATEMENT.....	Error! Bookmark not defined.
1.3 OBJECTIVES.....	Error! Bookmark not defined.
1.4 SCOPE OF STUDY.....	Error! Bookmark not defined.
1.5 RELEVANCY OF PROJECT.....	Error! Bookmark not defined.
1.6 FEASIBILITY OF PROJECT.....	Error! Bookmark not defined.
CHAPTER 2 : LITERATURE REVIEW AND THEORY.....	Error! Bookmark not defined.
2.2 UTILIZATION OF HYBRID FIBER COMPOSITES.....	Error! Bookmark not defined.
2.3 DRILLING IN COMPOSITE.....	Error! Bookmark not defined.
2.4 THEORY AND FUNDAMENTALS.....	Error! Bookmark not defined.
2.4.1 Types of Hybrid Composites.....	Error! Bookmark not defined.
2.4.2 Laminates.....	Error! Bookmark not defined.
2.4.3 Matrices (continuous phase).....	Error! Bookmark not defined.
2.4.4 Fiber Volume Fraction.....	Error! Bookmark not defined.
2.5 DRILLING PARAMETER.....	Error! Bookmark not defined.
2.5.1 Spindle Speed.....	Error! Bookmark not defined.
2.5.2 Feed Rate.....	Error! Bookmark not defined.
2.6 RESPONSE VARIABLES.....	Error! Bookmark not defined.
2.6.1 Damage Factor (FD).....	Error! Bookmark not defined.
2.6.2 Surface Roughness (Ra).....	Error! Bookmark not defined.

CHAPTER 3 : METHODOLOGY	Error! Bookmark not defined.
3.1 RESEARCH METHODOLOGY	Error! Bookmark not defined.
3.1.1 Flow Chart	Error! Bookmark not defined.
3.2.1 Carbon Fiber	Error! Bookmark not defined.
3.2.2 Glass Fiber	Error! Bookmark not defined.
3.3 PROJECT ACTIVITIES : Experimental Procedure	Error! Bookmark not defined.
3.3.1 Fabrication of hybrid fiber composite.....	Error! Bookmark not defined.
3.4 KEY MILESTONE.....	Error! Bookmark not defined.
3.5 GANTT CHART	Error! Bookmark not defined.
3.6 TOOLS (EQUIPMENT AND HARDWARE)	Error! Bookmark not defined.
3.7 SUMMARY OF PROJECT ACTIVITIES	Error! Bookmark not defined.
CHAPTER 4 : RESULT AND DISCUSSION	Error! Bookmark not defined.
4.1 THICKNESS OF SAMPLE.....	Error! Bookmark not defined.
4.2 RULES OF MIXTURE.....	Error! Bookmark not defined.
4.3 FABRICATED SAMPLES OF HYBRID FIBER COMPOSITE	Error! Bookmark not defined.
defined.	
4.4 DRILLING PARAMETERS	Error! Bookmark not defined.
4.5 DEFECTS OF THE DRILLED HOLES	Error! Bookmark not defined.
4.6 DAMAGE FACTOR	Error! Bookmark not defined.
4.6.1 Relationship between Spindle Speed (RPM) and Damage Factor, Fd at 0.05, 0.1 . and 0.2 mm/rev	Error! Bookmark not defined.
4.6.2 Relationship between Feed Rate (mm/rev) and Damage Factor, Fd at 1000, 2000 and 3000 rpm	Error! Bookmark not defined.
4.6.3 Effect of feed rate and spindle speed on damage factor	Error! Bookmark not defined.
4.6.4 3D Non Contact Images of the drilled holes entry	Error! Bookmark not defined.
4.7 AVERAGE SURFACE ROUGHNESS (Ra)	Error! Bookmark not defined.
4.7.1 Effect of feed rate on Ra at 1000, 2000, and 3000 rpm	Error! Bookmark not defined.
4.7.2 Effect of spindle speed on Ra at 0.05, 0.1 and 0.2 mm/rev	Error! Bookmark not defined.
4.8 MICROSTRUCTURAL ANALYSIS.....	Error! Bookmark not defined.
4.9 PROBLEMS FACED	Error! Bookmark not defined.
CHAPTER 5 : CONCLUSION.....	Error! Bookmark not defined.
REFERENCES.....	Error! Bookmark not defined.

