

## LIST OF FIGURES

Figure 2.1	Type I copper pitting corrosion	8
Figure 2.2	Type II copper pitting corrosion	8
Figure 2.3	Type III copper pitting corrosion	9
Figure 3.1	Metallography Processes	13
Figure 4.1	Microstructure of the copper tube at different locations. (Magnification 200x)	16
Figure 4.2	Grain Boundary revealed under SEM	17
Figure 4.3	The corroded copper tubes	18
Figure 4.4	$\text{CuCO}_3 \cdot \text{Cu}(\text{OH})_2$ , Malachite, The green area	19
Figure 4.5	$\text{Cu}(\text{OH})_x(\text{SO}_4)_y$ , Copper Sulfate and Cupric Salt, The blue area	19
Figure 4.6	The green/blue area of the copper tube under SEM	20
Figure 4.7	The black area of the copper tube under SEM	21
Figure 4.8	The EDS result of the greenish deposits found on the surface of the tubes.	22

## LIST OF TABLES

Table 4.1	The effect of various water constituents and characteristics on Type I pitting	24
-----------	---	----